

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/07/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/03/12 – 0700, 05/10/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	Operational status: <ul style="list-style-type: none"> <li>• Source Area Pond, sheen observed.</li> <li>• Ceresco Dam legacy project, sheen observed.</li> <li>• Ceresco Dam, sheen observed within containment.</li> <li>• Ceresco Dam, sheen observed going over dam.</li> <li>• OB5.92 RDB, observed crews inspecting pond.</li> <li>• OB5.92 RDB, observed crew performing sheen test.</li> <li>• C0.4 Boat launch, sheen observed.</li> <li>• C0.4 Boat launch, observed boats staging for boater training.</li> </ul>		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			